



City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

195-201 Main Street Housing Reinspection Report January 15th, 2019 at 1:00 P.M.

Stephen Yerly, John Hester, Melania Pervu, Kenneth Williams and unidentified female were present. The owner and/or her agents videotaped the inspection.

Summary: Many of the code violations noted in the original report still exist throughout the building. Notations below show the observed violations in each room or area of the inspected premises. Photos are attached.

General Notes on Conditions at the Inspected Premises:

- -A licensed plumber has made plumbing corrections throughout the building. Though the piping was installed correctly, many of the vanities and cabinet units in the apartments still require replacement due to deteriorated condition and water damage.
- -Many of the apartment units still have non-compliant floor, ceiling and wall coverings due to damaged or deteriorated conditions as well as an overall lack of cleanliness. Some units have had new flooring installed; apparently over the existing flooring. It is hard to determine if this flooring was installed per the manufactures specifications. It does not appear to have been done professionally.
- The sprinkler system is now blocked by non compliant suspended ceiling tiles installed beneath the sprinkler pipes throughout the building. These tiles are not rated for installation below an automatic sprinkler system. These tiles would block or hinder the fire suppression capability of the system in the event they are triggered by a fire.
- -There are portions of the building that are currently under various states of demolition and/or construction. These areas are not ready for a final inspection.





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

-This property currently has many significant Code violations and will require a re-inspection and be in compliance with the appropriate codes prior to the granting of a Certificate of Compliance.

SPECIFIC VIOLATIONS

Apt. 5A

· Living room ceiling, signs of water damage

Apt. 5H

- Rear Hall- smoke detector not installed
- Rear Hall door leading to rear exit stairway is hollow core
- Shower surround deteriorated
- Ceiling tiles show signs of water damage. Disrepair

Apt. 5I

- Light installed in hood vent is inoperable
- Bathroom shower/tub wall is repaired with duct tape, not to generally accepted standards
- Rear bedroom- no smoke detector installed

Apt. 5B

- Entry door damaged near door knob
- Carpet in poor condition
- Damage on base of wall between living area and kitchen

Apt. 5G

Ceiling has signs of water damage and possible active water leak





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

Apt. 5C

Hood fan installed over kitchen range is inoperable

Apt. 5D

• Floor/ceiling has signs of water damage

Apt. 5F

 Interior walls abutting common hallway are bare studs (fire separation is not in place)

<u> Apt. 5G</u>

 Poor condition (signs of water leaks, bare studs, lath and plaster missing and contains large holes, fire separations compromised)

Apt. 5E

Ceilings have signs of water damage

Room 403

- bathroom sink continuously dripping
- no cooking facilities
 - Door knob missing from bedroom door

Room 405

smoke detector inoperable

Room 406

- Electrical breakers inside wood paneled room are unlabeled
- Smoke detector mounted too high on wall
- Door frame inside bedroom leading to hallway is damaged/cracked





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

Room 410

missing smoke detector outside of bedroom

Room 414

- missing smoke detector outside of bedroom
- Baseboard heating element covers loose or unattached

Room 417

no access

Room 420

installed smoke detectors are over 10 years old (expired)

Room 423

• Room does not contain a kitchen sink, cooking appliance or refrigerator

Room 424

bathroom sink contains s-trap

Room 428

- Bathroom does not have proper ventilation
- Baseboard heating element covers loose or unattached

Fourth Floor Hallway

- Floor covering is ripped at seams, tripping hazard
- rear exit light is not illuminated leading to egress window to fire escape





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

Fourth Floor Thermostat Room

- plumbing pipes penetrating common hallway wall are not fire caulked
- portions of lath and plaster wall covering missing around plumbing waste line
- lath and plaster has large hole in ceiling (fire separation compromised)

4th Floor electrical panel room

Breakers not labeled

Room 301

- no cooking facilities
- flooring throughout unit is filthy
- wall vanity installed 4-6 inches away from wall
- shower pan and walls are filthy

Room 304-(no access)

Room 305

- light inoperable on the kitchen hood range
- living room ceiling tiles have water stains
- bottom of sheetrock wall that meets bathtub is deteriorated and water damaged

Room 310

- Smoke detector located in the living room has no battery
- Smoke detector is not installed in area between bedroom and kitchen
- Wall vanity not installed against wall





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

Room 312

- Bathroom door missing
- Bathroom-Metal threshold loose (tripping hazard)

Room 317

• Baseboard heating element covers loose or unattached

Room 320

smoke detectors are expired, over 10 years old

Room 323

- · no cooking facilities
- shower pan filthy

Room 324

- no cooking facilities
- baseboard heating element cover loose/unattached or damaged

Room 325

bottom of sheetrock wall where wall meets bathtub

Room 328

- Tile wall covering missing where wall meets tub
- Bathroom- rear of bathtub to left of sink repair not to generally accepted standards
- Hasp style lock installed on bedroom door

3rd floor rear stairway- storage room off landing

- room appears to be full of personal belongings/discarded items/trash
- large hole in rear wall near plumbing cleanout





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

3rd floor room (labeled Men's Room)

- portion of sheetrock missing near plumbing waste line
- heavy peeling paint

3rd floor- hallway

- Floor covering torn at seams, tripping hazards
- Smoke detector located in front of elevator is not seated flush on ceiling surface

Apt. 2A

- additional smoke detector should be installed between front door and hallway leading to rear bedroom
- bedroom smoke detector is mounted too high on wall
- bathroom- hole in wall behind toilet

Room 2B

- entry door should be self closing
- wall and floor near bathtub are water damaged/deteriorated
- rear bedroom- baseboard heating element covers loose or disconnected

Apt. 204

- kitchen storm window cracked
- entry door should be self closing

Room 206

missing smoke detector in bedroom

Room 210

- double keyed lock on bedroom door
- baseboard heating element cover loose/unattached or damaged





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

Room 222

smoke detector missing in bedroom

2nd floor rear stairway

- panel located behind door entering apt. 2B- breakers are not fully labeled.
- Electrical wiring passing into apartment from stairwell are not fire caulked

2nd floor room (labeled service room)

Evidence of active water leak

Basement

- Main sprinkler water flow valve unlocked
- East boiler room, unlabeled electrical panel- breakers are not labeled and breaker directory is upside down
- Basement area of Tiger Asian restaurant smoke detector is beeping, improperly installed plumbing (sink waste line), standing water near grease trap (grease trap appears to be overflowing with grease)
- West Boiler room- water line from boiler has severe corrosion and active water leak, lath and plaster missing rear of room (fire separation compromised)
- Ceiling just outside of west boiler room is missing lath and plaster (fire separation is compromised)
- Rear exit stairway leading from basement- egress restricted (fiberglass ladder, bookcase and other furniture blocking egress)

Elevator:

No record of inspection





City Hall, 258 Main Street Oneonta, NY 13820-2589 Phone: 607.433-3435
Fax: 607.432-0945
Internet Address:
www.oneonta.ny.us
E-Mail Address:
codeenforcement@oneonta.ny.us

Sprinkler:

- Ceiling grid suspended from pipe. Electrical wire on pipe.
- Sprinkler heads located above drop ceiling tiles.

Electrical Inspection:

• Final electrical violation report has not been provided as clear

This property will require a re-inspection prior to the issuance of a Certificate of Compliance, as there are significant outstanding violations.